

William Cundiff

From: Robert Anders [lhanders3@aol.com]
Sent: Sunday, January 23, 2011 4:53 PM
To: wCundiff@DouglasMa.org
Subject: Fwd: Vestas Turbine Safety and Operations Manual

Begin forwarded message:

From: Eric Bibler <ebibler@gmail.com>
Date: January 23, 2011 2:12:42 PM EST
To: Eric Bibler <ebibler@gmail.com>
Subject: Fwd: Vestas Turbine Safety and Operations Manual
Return-Path: <randers+caf_lhanders3=aol.com@blueberryhillassociation.com>
Received: from mtain-dd07.r1000.mx.aol.com (mtain-dd07.r1000.mx.aol.com [172.29.64.147]) by air-me08.mail.aol.com (v129.4) with ESMTMP id MAILINME084-8bbf4d3c7db0227; Sun, 23 Jan 2011 14:12:48 -0500
Received: from mail-qw0-f52.google.com (mail-qw0-f52.google.com [209.85.216.52]) by mtain-dd07.r1000.mx.aol.com (Internet Inbound) with ESMTMP id A6CC23800106 for <lhanders3@aol.com>; Sun, 23 Jan 2011 14:12:47 -0500 (EST)
Received: by mail-qw0-f52.google.com with SMTP id 4so4494302qwi.25 for <lhanders3@aol.com>; Sun, 23 Jan 2011 11:12:47 -0800 (PST)
Received: by 10.224.74.80 with SMTP id t16mr3281659qaj.0.1295809967410; Sun, 23 Jan 2011 11:12:47 -0800 (PST)
Received: by 10.220.188.137 with SMTP id da9cs14822vcb; Sun, 23 Jan 2011 11:12:47 -0800 (PST)
Received: by 10.227.155.9 with SMTP id q9mr1811640wbw.32.1295809965872; Sun, 23 Jan 2011 11:12:45 -0800 (PST)
Received: from mail-ww0-f53.google.com (mail-ww0-f53.google.com [74.125.82.53]) by mx.google.com with ESMTMP id o13si18933423wee.56.2011.01.23.11.12.44 (version=TLSv1/SSLv3 cipher=RC4-MD5); Sun, 23 Jan 2011 11:12:44 -0800 (PST)
Received: by wwi18 with SMTP id 18so3800507wwi.34 for <multiple recipients>; Sun, 23 Jan 2011 11:12:44 -0800 (PST)
Received: by 10.227.144.9 with SMTP id x9mr3356011wbu.103.1295809962423; Sun, 23 Jan 2011 11:12:42 -0800 (PST)
Received: by 10.227.147.203 with HTTP; Sun, 23 Jan 2011 11:12:42 -0800 (PST)
X-Forwarded-To: lhanders3@aol.com
X-Forwarded-For: randers@blueberryhillassociation.com lhanders3@aol.com
Delivered-To: randers@blueberryhillassociation.com
Received-Spf: pass (google.com: domain of ebibler@gmail.com designates 74.125.82.53 as permitted sender) client-ip=74.125.82.53;
Authentication-Results: mx.google.com; spf=pass (google.com: domain of ebibler@gmail.com designates 74.125.82.53 as permitted sender) smtp.mail=ebibler@gmail.com; dkim=pass (test mode) header.i=@gmail.com
Dkim-Signature: v=1; a=rsa-sha256; c=relaxed/relaxed; d=gmail.com; s=gamma; h=domainkey-signature:mime-version:in-reply-to:references:date:message-id:subject:from:to:content-type; bh=XjXOkCCqP8t9oxocYjUXeGDd5tkCpSdhgFOzRFnRQbo=; b=BKtFQAg1vW8DSseWKV5xMsOutis6Q7AXzkz/28EdwZrMuqzZv5mdk0Tjzp+UjMwWN
RU+h3rMI38MkAeQFzz5WgKrhfADWA6o7rKlsxayF8JKZGdhIKLhi3sPP/Hn4fvXEWLRS
TQpiyEK3J44D99TEYTrF6KW42idvstNjNbEBU=
Domainkey-Signature: a=rsa-sha1; c=noaws; d=gmail.com; s=gamma; h=mime-version:in-reply-to:references:date:message-id:subject:from:to:content-type; b=Cd7ESaqhgx/ln+f8xi3VjNe3/8fg3A0LTN7dChURjVQ8aEt8GKS4IIQRTfchB64ij5
gG0tB9U73bYj7clFUPkNVXW6fn401b+EtmrtTMRCGBkMFbP/k3gjY++/0tYr8Ei6RNBQ
3fjRcEg1TUria2XyeM1TUGMp35RKjwLQ4kYr0=
Mime-Version: 1.0
In-Reply-To: <20110123092100.h4jk5c7scgk8kk@webmail.carrinter.net>
References: <20110123092100.h4jk5c7scgk8kk@webmail.carrinter.net>
Message-Id: <AANLkTimYqKUXDHXQ++EL=UfHM9sXtgsCKw1B=V1fmUTO@mail.gmail.com>
Content-Type: multipart/alternative; boundary=0016364efa4c81bd46049a88445c
X-Aol-Global-Disposition: G
X-Aol-Scroll-Authentication: mail_rly_antispam_dkim-d279.1; domain: gmail.com DKIM: pass
X-Aol-Sid: 3039ac1d40934d3c7daf07fe
X-Aol-Ip: 209.85.216.52
X-Mailer: Unknown (No Version)

All,

See the note below from someone in the same boat -- in MI.

I just re-read the Vestas Safety manual and the reference occurs in the section entitled "Stay and Traffic by the Turbine."

Notice that it does not appear in the: *"Holy Mother of God the Thing is On Fire -- That Almost NEVER Happens -- and Will Probably Never Happen Again -- Run for Your Life, Just This Once!"* section of the manual.

Eric

----- Forwarded message -----

From: <pdi@carrinter.net>

Date: Sun, Jan 23, 2011 at 9:21 AM

Subject: Vestas Turbine Safety and Operations Manual

To: ebibler@gmail.com

Eric-

You are absolutely right that this is nothing more than a public relations stunt.

Engineering, maintenance, and operations manuals are carefully written.

The manual clearly stated what it stated. I am sure you have the manual.

These documents are carefully written, reviewed, and approved by technical personnel.

To think that in their Safety portion of a manual, this type of oversight would be, just a typo is, well quite frankly, unbelievable.

The bottom line from Vestas is that they are shutting down manufacturing operations in europe and trying to dominate a U.S. market where inadequate zoning allows for turbines to be placed within what the company formerly was comfortable with.

We have the same response as I posed the same question here in Western Michigan with the same insincere response.

Good luck with the challenges you face.

My heart, thoughts, and prayers are with you and the people you are actively trying to protect. You are on the right side of this. Tell your people, for what its worth, that from my home overlooking the rolling hills and orchards of Michigan, I and my neighbors support your efforts. We are in the same unbelievable battle for you lives and homes.

Keep up the good work.

Sincerely:

Cary Shindeldecker
Riverton Township, Mason County, Michigan